Non-Compliance Notice - Issued

Permit Holder: Tidewater Midstream and Infrastructure Ltd.
Discovery Date: 2026-11-18
As a result of Inspection2026-3714

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: **2026-0718-01** Issued Date: **'2026-11-19'** Status: **Issued** Outcome: Correction Duration: **14 Days** Correction Due Date: **'2026-12-03'**	Permit: 100063082 Well ID: 23718 Well Name: TIDEWATER KELLY D- 017-J/093-P-01 Location: NTS: D- 017-J/093-P-01 Legislation: Energy Resource Activities Act - 37 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage; (b) contain and eliminate the spillage;
Non-Compliance Comment: Lel's in meter box caused personal monitor to alarm.	

_____

Authorized by BCER