Non-Compliance Notice - Issued

Permit Holder: Aduro Resources Ltd.
Discovery Date: 2026-11-23
As a result of Inspection2026-3844

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: **2026-0743-01** Issued Date: **'2026-11-25'** Status: **Issued** Outcome: Correction Duration: **30 Days** Correction Due Date: **'2026-12-25'**	Permit: 100026873 Well ID: 12913 Well Name: ADU MONIAS 06-35-082-23 Location: DLS: 06-35-082-23 Legislation: Drilling and Production Regulation 41 (4) On discovery of a surface casing vent flow other than one referred to in subsection (3), a well permit holder must (b) submit a surface casing vent flow report to the commission within 30 days of the discovery of the surface casing vent flow.

Non-Compliance Comment: A noticeable smell of gas was present on lease in the area of the wellhead, the
SCV was checked and found to be actively leaking.

_____

Authorized by BCER