

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-1520
Inspection Date: 2026-05-07
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-Disconnected pumpjack remains in place with head on. Wellhead valves chained and locked and flowline is disconnected from the wellhead. No SCVF

-lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100009151
Well ID: 06262
Well Name: WHITECAP ET AL BOUNDARY 04-23-084-14
Location: DLS: 04-23-084-14

Authorized by BCER