

Inspection Report

Permit Holder: Shell Canada Limited
Inspection: 2026-1551
Inspection Date: 2026-05-12
Inspection Outcome: Inspected

Inspection Comment:

4-10-81-20

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve was locked/car sealed.

Bettis actuator no concerns.

Metering cabinet no concerns.

Pigging area no concerns.

All plugs and caps were in place.

No concerns identified at time of site inspection.

A4-10-81-20

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve was locked/car sealed.

Bettis actuator no concerns.

Metering cabinet no concerns.

Pigging area no concerns.

All plugs and caps were in place.

No concerns identified at time of site inspection.

B4-10-81-20

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve was locked/car sealed.

Bettis actuator no concerns.

Metering cabinet no concerns.

Pigging area no concerns.

All plugs and caps were in place.

No concerns identified at time of site inspection.

C4-10-81-20 Signage no concerns.

SCV no venting observed.

Shutdown isolation valve was locked/car sealed.

Bettis actuator no concerns.

Metering cabinet no concerns.

Pigging area no concerns.

All plugs and caps were in place.

No concerns identified at time of site inspection.

D4-10-81-20 Signage no concerns.

SCV no venting observed.

Shutdown isolation valve was locked/car sealed.

Bettis actuator no concerns.

Metering cabinet no concerns.

Pigging area no concerns.

All plugs and caps were in place.

No concerns identified at time of site inspection.

Methanol tank with secondary containment in place.

Chemical injection system no concerns.

Desander no concerns.

Separator NWP 09657 001 no concerns.

Separator NWP 43728 001 no concerns.

RTU BU-62100 building no concerns.

Sirius chemical injection system no concerns.

Pigging area no concerns.

No concerns identified at time of site inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100081832

Well ID: 31132

Well Name: SHELL ET AL HZ GROUNDBIRCH 04-10-081-20

Location: DLS: 04-10-081-20

Permit: 100081833

Well ID: 31133

Well Name: SHELL ET AL HZ GROUNDBIRCH A04-10-081-20

Location: DLS: A04-10-081-20

Permit: 100081834
Well ID: 31134
Well Name: SHELL ET AL HZ GROUNDBIRCH B04-10-081-20
Location: DLS: B04-10-081-20

Permit: 100081835
Well ID: 31135
Well Name: SHELL ET AL HZ GROUNDBIRCH C04-10-081-20
Location: DLS: C04-10-081-20

Permit: 100081836
Well ID: 31136
Well Name: SHELL ET AL HZ GROUNDBIRCH D04-10-081-20
Location: DLS: D04-10-081-20

Permit: 100081832
Facility ID: 00018347
Facility Name: SHELL GROUNDBIRCH 04-10-081-20 001
Facility Type: Well Facility
Location: DLS: 04-10-081-20

Authorized by BCER