

Inspection Report

Permit Holder: Strathcona Resources Ltd.
Inspection: 2026-1664
Inspection Date: 2026-05-21
Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1520HRS.

Access road- Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. Location is within a swamp. Wellhead is surrounded by water.

Lease Equipment: Well is listed as an observation well. Barricades in place. Signage (Faded) in place at entrance. Flow lines removed. Valve handles are chained and locked. 1 valve handle not chained and locked (See attached).

Surface casing vent flow test- Flow detected from glove test, Glove filled in less than 1 min. LEL detected upon removal of glove- No alarms on personal monitor. Performed bubble test from 1522-1532- approx 2 bubbles observed.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100017662
Well ID: 09369
Well Name: STRATHCONA RIGEL 01-34-088-18
Location: DLS: 01-34-088-18

Authorized by BCER