

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-1702
Inspection Date: 2026-05-22
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-active electric pumpjack. No SCVF

-there is a location sign propped up on the pumpjack that reads: 5-2-85-14. This is not correct. I turned the sign over and laid it on the pumpjack skid.

-in the IRIS database, the wells listed for this location are:

6-2-85-14 WA# 501 status is Abandoned

A6-2-85-14 WA#6223 status is Active

B6-2-85-14 WA#30677 status is Cancelled

C6-2-85-14 WA#2911 status is Active

Please ensure the location signage is correct at each well

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100003876
Well ID: 02911
Well Name: WHITECAP BOUNDARY C06-02-085-14
Location: DLS: C06-02-085-14

Permit: 100003876
Facility ID: 00018619
Facility Name: WHITECAP BOUNDARYLAKE 06-02-085-14 002
Facility Type: Well Facility
Location: DLS: 06-02-085-14



Inspection Number: 2026-1702
Inspection Date: 2026-05-22

Letter ID: L2602412
Letter Date: 2026-05-26

Authorized by BCER