

## Inspection Report

Permit Holder: Tourmaline Oil Corp.  
Inspection: 2026-1747  
Inspection Date: 2026-05-28  
Inspection Outcome: Non-Compliance(s) Found

### Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1417HRS.

Access road- No concerns at the time of inspection.

Lease Equipment: Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place (. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- Glove filled immediately. Performed bubble test at 1421- immediate ongoing bubbling (See attached). no Surface casing pressure test appears to have been performed according to BCER internal records.

Officer requests company perform a Surface casing Vent pressure test and submit to BCER within 30 days.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100025573  
Well ID: 12464  
Well Name: TOURMALINE MARTIN D- 094-D/094-H-06  
Location: NTS: D- 094-D/094-H-06

---

Authorized by BCER