

Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-1780
Inspection Date: 2026-05-28
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- Inactive pumpjack. No SCVF
- there is no chain and lock on the wellhead valves. The flowline is disconnected from the wellhead. This well has not produced since May 2024. In order to achieve proper surface suspension, the wellhead valves need to be chained and locked, as well.
- pumpjack remains connected to the polish rod.
- lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100029088
Well ID: 13905
Well Name: SABA O&G BOUNDARY 07-22-085-14
Location: DLS: 07-22-085-14

Authorized by BCER