

## Inspection Report

Permit Holder: Yoho Resources Inc.  
Inspection: 2026-1824  
Inspection Date: 2026-05-28  
Inspection Outcome: Inspected

### Inspection Comment:

This inspection is a Risk and Data Informed inspection from a previous list. For the pipeline riser, the ground wire needs to be connected to the containment bin.

In the line heater skid, the fuel gas PSHH piping has been changed and is compliant in its setup. The section of piping with the ball valve has been disconnected and bull plugged. Please see inspection 2026-1822 for location 11-24-87-24 and the same piping is set up.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100106754  
Well ID: 37641  
Well Name: YOHO HZ INGA 03-14-087-24  
Location: DLS: 03-14-087-24

Permit: 100107973  
Well ID: 38798  
Well Name: YOHO HZ INGA A03-14-087-24  
Location: DLS: A03-14-087-24

Permit: 100109144  
Facility ID: 00027066  
Facility Name: YOHO INGA 03-14-087-24 001  
Facility Type: Well Facility  
Location: DLS: 03-14-087-24

---

Authorized by BCER