

## Inspection Report

Permit Holder: Whitecap Resources Inc.  
Inspection: 2026-1893  
Inspection Date: 2026-06-03  
Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

-wellhead valves chained and locked. Flowline is disconnected from the wellhead and at pipeline end. Electric pumpjack inactive in place with no polish rod.

-No SCVF.

-lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100067500  
Well ID: 24909  
Well Name: WHITECAP BOUNDARY 10-25-085-14  
Location: DLS: 10-25-085-14

Permit: 100067500  
Facility ID: 00023924  
Facility Name: WHITECAP BOUNDARYLAKE 10-25-085-14 001  
Facility Type: Well Facility  
Location: DLS: 10-25-085-14

---

Authorized by BCER