

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-2018
Inspection Date: 2026-06-11
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-H2O injection with cover.

-No SCVF but is missing the handle. If the handle that is there (partially buried) is for the SCV, it does not look to be usable.

-lease and access are compliant. The location signage is not at the well but is approximately 500 meters down the access road at the gate. Access road is rutted up.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001869
Well ID: 01400
Well Name: WHITECAP ET AL BOUNDARY 08-29-084-13
Location: DLS: 08-29-084-13

Authorized by BCER