

Inspection Report

Permit Holder: Whitecap Resources Inc.

Inspection: 2026-2651

Inspection Date: 2026-07-23

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-wellhead valves chained and locked. Flowline is disconnected from the wellhead. Pumpjack disconnected in place. As per Whitecap.... "A Poor Man's Suspension" with polish rod remaining in well without being connected to the pumpjack. This is not in line with the BCER Guidelines.

-No SCVF

-lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001230

Well ID: 00949

Well Name: WHITECAP ET AL BOUNDARY 06-08-086-13

Location: DLS: 06-08-086-13

Authorized by BCER