

Inspection Report

Permit Holder: Whitecap Resources Inc.

Inspection: 2026-2664

Inspection Date: 2026-07-23

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-wellhead valves chained and locked. Flowline is disconnected from the wellhead.
Pumpjack disconnected from polish rod and in place.

-No SCVF

-lease, access and location signage is compliant.

-the header building has piping disconnected. When or if put back into use, the
catadyne hood vent is corroded and needs replaced.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001061

Well ID: 00811

Well Name: WHITECAP ET AL BOUNDARY 06-18-086-13

Location: DLS: 06-18-086-13

Authorized by BCER