

Inspection Report

Permit Holder: Whitecap Resources Inc.

Inspection: 2026-2677

Inspection Date: 2026-07-23

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-wellhead valves chained and locked. Flowline is disconnected from the wellhead. Pumpjack remains in place disconnected from polish rod. Polish rod remains in the wellhead in what Whitecap has called a "poor mans suspension".

-No SCVF

-lease and access are compliant. Location signage is hidden/overgrown with vegetation and needs to be "conspicuous" as per the Regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001347

Well ID: 01050

Well Name: WHITECAP ET AL BOUNDARY 06-30-086-13

Location: DLS: 06-30-086-13

Authorized by BCER