

Inspection Report

Permit Holder: Whitecap Resources Inc.

Inspection: 2026-2770

Inspection Date: 2026-07-30

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-electric pumpjack inactive at time of inspection. Wellhead valves not chained and locked. Flowline is not disconnected from the wellhead. Pumpjack remains in place connected to the polish rod. No SCVF

-lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100003160

Well ID: 02375

Well Name: WHITECAP ET AL BOUNDARY 07-01-086-14

Location: DLS: 07-01-086-14

Authorized by BCER