

Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-2777
Inspection Date: 2026-07-30
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- active H2O injection with cover. No SCVF
- there is a Taqa North sign that states there is no SCV on this well. What looks to be the SCV has been plugged and the sign says that is should be. Why is that?
- lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001911
Well ID: 01440
Well Name: SABA O&G BOUNDARY 06-02-086-14
Location: DLS: 06-02-086-14

Authorized by BCER