

Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-2780
Inspection Date: 2026-07-30
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

COMMENTS:

-electric pumpjack inactive at time of inspection. As per the database, this well has not produced since December 2023. The wellhead valves are not chained and locked and the flowline is not disconnected from the wellhead. Pumpjack remains in place connected to the polish rod.

-No SCVF

-location signage at the lease entrance has both sour and flammable symbols, but the location signage on the pumpjack does not have a sour symbol. These two signs for this same well should be the same.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001514
Well ID: 01156
Well Name: SABA O&G BOUNDARY 08-03-086-14
Location: DLS: 08-03-086-14

Authorized by BCER