

Inspection Report

Permit Holder: ConocoPhillips Canada Resources Corp.

Inspection: 2026-2876

Inspection Date: 2026-08-11

Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1110HRS.

Access road- Very muddy. No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. Barricades in place. Signage in place at entrance. Positive isolation maintained (flow lines removed). Valve Handles chained, lock not secure (see attached). Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor. Building out of service.

Pig Station- Out of service

Tanks and secondary containment on site- containment completely full of fluid (See attached).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100012240

Well ID: 07519

Well Name: COP FIREWEED B- 050-D/094-A-14

Location: NTS: B- 050-D/094-A-14

Authorized by BCER



Inspection Number: 2026-2876
Inspection Date: 2026-08-11

Letter ID: L2604087
Letter Date: 2026-08-12