

Inspection Report

Permit Holder: ConocoPhillips Canada Resources Corp.

Inspection: 2026-2877

Inspection Date: 2026-08-11

Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1133HRS.

Access road- Very muddy. Road has rutted tire tracks in areas. No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. Barricades in place. Signage in place at entrance. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure (wing valve handle not chained & locked or removed).

Surface casing vent flow test- No Flow detected from glove test.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100059095

Well ID: 22660

Well Name: COP FIREWEED D- 030-D/094-A-14

Location: NTS: D- 030-D/094-A-14

Permit: 100059095

Facility ID: 00022753

Facility Name: COP FIREWEED D-030-D/094-A-14 001

Facility Type: Well Facility

Location: NTS: D- 030-D/094-A-14

Authorized by BCER



Inspection Number: 2026-2877
Inspection Date: 2026-08-11

Letter ID: L2604090
Letter Date: 2026-08-12