

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-2912

Inspection Date: 2026-08-11

Inspection Outcome: Inspected

Inspection Comment:

The pressure indicator transmitters on the 11-16 and a-11-16 flowlines only have 1 ball valve locked in the open position. The other ball valve located above is not locked in the open position. Are these transmitters part of the the ESD shutdown function? If so, all ball valves need to be locked in the open position. Please notify the inspector by email as to the ESD function of these transmitters. Thank you

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100074570

Well ID: 27774

Well Name: CNRL HZ ALTARES 11-16-083-25

Location: DLS: 11-16-083-25

Permit: 100075510

Well ID: 28090

Well Name: CNRL HZ ALTARES B11-16-083-25

Location: DLS: B11-16-083-25

Permit: 100075543

Well ID: 28088

Well Name: CNRL HZ ALTARES A11-16-083-25

Location: DLS: A11-16-083-25

Permit: 100074570

Facility ID: 00025366

Facility Name: CNRL NORTHERNMONTNEY 11-16-083-25 001

Facility Type: Well Facility

Location: DLS: 11-16-083-25

Permit: 100075510

Facility ID: 00025482

Facility Name: CNRL NORTHERNMONTNEY 11-16-083-25 002

Facility Type: Well Facility

Location: DLS: 11-16-083-25

Permit: 100075543
Facility ID: 00025481
Facility Name: CNRL NORTHERNMONTNEY 11-16-083-25 003
Facility Type: Well Facility
Location: DLS: 11-16-083-25

Authorized by BCER