

Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-3200
Inspection Date: 2026-09-02
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

WA# 809 - Sept. 2, 2026: 12:10. on site.

Wellhead: SCVA ball valve handle was found in the open position, no LEL gas was measured (Altair-5x), and no flow was observed. Flowline not disconnected / suspended and valve handles not chained and locked.

Kermit last reported gas production rate: 2025-03 "Suspended Status".

Signage is compliant to standards.

Well Facility: Cata-Dyne regulator vent lines are present: Suspended Status.

Storage: single wall tanks in plastic containment, SDS labels present, and grounded.

Flowline: flowline is connected to the wellhead, well building, and pipeline (Suspended Status). Snake wrap is hanging/detaching from flowline: maintenance may be required in the future to avoid debris being scattered onto well pad.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001059
Well ID: 00809
Well Name: SABA O&G LAPRISE D- 091-H/094-G-08
Location: NTS: D- 091-H/094-G-08

Authorized by BCER