

Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-3259
Inspection Date: 2026-09-02
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

A# 23298 - Sept. 2, 2026: 11:06 on site.

Wellhead: SCVA ball valve handle was found in the open position, no LEL gas was measured (Altair-5x), and no flow was observed. Flowline is not disconnected / suspended, and valve handles present (4x) which are not chained and locked.

Kermit last reported gas production rate: 2025-03 "Suspended Status".

Signage is compliant to standards.

Well Facility: Cata-Dyne regulator vent lines are present: Suspended Status.

Storage: single wall tank in plastic secondary containment, SDS labels present, and grounded.

Flowline: flowline is connected to the wellhead, well building, and pipeline (Suspended Status).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100062089
Well ID: 23298
Well Name: SABA O&G ET AL LAPRISE D- 090-E/094-H-05
Location: NTS: D- 090-E/094-H-05

Permit: 100062089
Facility ID: 00023045
Facility Name: SABA O&G LAPRISECREEK D-090-E/094-H-05 001
Facility Type: Well Facility
Location: NTS: D- 090-E/094-H-05



Inspection Number: 2026-3259
Inspection Date: 2026-09-02

Letter ID: L2604619
Letter Date: 2026-09-09

Authorized by BCER