

Inspection Report

Permit Holder: NorthRiver Midstream Inc.

Inspection: 2026-3275

Inspection Date: 2026-09-03

Inspection Outcome: Inspected

Inspection Comment:

WA# 14304 and 23148 (A) - Sept. 3, 2026: 9:45 hrs. on site.

Wellheads (2x): SCVA ball valve handle was found in the open position, client is monitoring/reporting SCVF to standards/requirements. Wellheads are in suspended status: flowline disconnected and all well valve handles are chained/locked.

Signage is compliant to standards.

Well Facility: Suspended Status - out of service:

Storage: no storage tanks are found/used on site.

Flowline: flowlines are disconnected to the wellheads, well buildings, and pipelines (Suspended Status).

Scentless Chamomile was noted on site.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100031444

Well ID: 14235

Well Name: NORTHRIVER BUBBLES D- 098-I/094-G-01

Location: NTS: D- 098-I/094-G-01

Permit: 100063201

Well ID: 23757

Well Name: NORTHRIVER BUBBLES D-A098-I/094-G-01

Location: NTS: D-A098-I/094-G-01

Authorized by BCER