

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.

Inspection: 2026-3285

Inspection Date: 2026-09-03

Inspection Outcome: Inspected

Inspection Comment:

WA# 541 - Sept. 3, 2026: 12:50 on site.

Wellhead: SCVA ball valve handle was found in the open position, no LEL gas was measured, and no flow was observed. Wellhead lower wing valve handle (1x) is present but is not either chained & locked (chained & locked or removed is required for suspended status). Flowline is disconnected to wellhead.

Kermi last reported gas production rate: 2024-10 "Suspended Status".

Signage is compliant to standards.

Well Facility: Suspended Status - Out of Service

Storage: double wall tank (1x) in metal containment, SDS labels are posted, and tank is grounded (Out of Service).

Flowline: flowline is disconnected to the wellhead, facility, and pipeline (Suspended Status).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100000691

Well ID: 00541

Well Name: PETRONAS ET AL BEG D- 010-G/094-G-01

Location: NTS: D- 010-G/094-G-01

Authorized by BCER