

Inspection Report

Permit Holder: Pacific Canbriam Energy Limited

Inspection: 2026-3303

Inspection Date: 2026-09-11

Inspection Outcome: Inspected

Inspection Comment:

This is a follow up for the original inspection #2026-
[https://cmis.bc-er.ca/noncompliance/3959/6728]1400 conducted in June 2026.
While one response was received of the 3 deficiencies, there are 2 deficiencies
in CMIS that require a response to. These were regarding leaks revealed by
bubbling water from the wellhead cellars.

I stopped by the site on Friday September 11, 2026 and noticed 2 of the 3 well
cellars were emptied of their water, however, the 3rd cellar (c-23-H) was still
full of water and bubbling was observed coming from further down the wellhead.
The other well head (c-a-23-H) where bubbling was noticed in the June inspection
was emptied of water so it is not known if the leak was addressed.

Please have the active c-23-h leak repaired and confirm that c-a-93-H leak was
fixed. You can respond to the original inspection 2026-1400 where the
deficiencies reside waiting for your response.

Thank you

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100073877

Well ID: 27196

Well Name: PACIFIC CANBRIAM HZ ALTARES C- 023-H/094-B-08

Location: NTS: C- 023-H/094-B-08

Permit: 100073878

Well ID: 27242

Well Name: PACIFIC CANBRIAM HZ ALTARES C-A023-H/094-B-08

Location: NTS: C-A023-H/094-B-08

Authorized by BCER



Inspection Number: 2026-3303
Inspection Date: 2026-09-11

Letter ID: L2604688
Letter Date: 2026-09-14