

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-3381
Inspection Date: 2026-09-22
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1430HRS.

Access road- Fallen tree along road causing obstruction (see attached). No other concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. Barricades in place. Signage in place at entrance. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Plug missing on T connection coming from needle valve (See attached). Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor. Building out of service.

Pig Station- safety chain not attached to PAV, signage indicates line deactivated. No concerns at time of inspection.

Tanks on site-Out of service.

Flare on site- Out of service.

Note: Various discarded equipment laying around lease (See attached).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100016490
Well ID: 08940
Well Name: PETRONAS ET AL JEDNEY C- 046-H/094-G-01
Location: NTS: C- 046-H/094-G-01

Authorized by BCER