

## Non-Compliance Notice - Issued

Permit Holder: Ovintiv Canada ULC  
Discovery Date: 2026-04-30  
As a result of Inspection 2026-1388

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p><b>Non-Compliance Number:</b> <b>2026-0275-01</b></p> <p><b>Issued Date:</b> <b>'2026-05-05'</b></p> <p><b>Status:</b> <b>Issued</b></p> <p><b>Outcome:</b></p> <p><b>Correction Duration:</b> <b>30 Days</b></p> <p><b>Correction Due Date:</b> <b>'2026-06-04'</b></p>	<p>Permit: 100105294 Well ID: 37093 Well Name: OVV HZ TOWERLAKE K05-02-081-17 Location: DLS: K05-02-081-17</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;</p>
<p>Non-Compliance Comment: K 05-02 - packing and stain</p> <p>L 05-02 - packing and stain</p> <p>N05-02 - packing and stain</p> <p>O05-02 packing and stain</p>	

---

Authorized by BCER