

Non-Compliance Notice - Issued

Permit Holder: PETRONAS Energy Canada Ltd.
Discovery Date: 2026-05-08
As a result of Inspection 2026-1523

Notice Comment:

b-E28-B - wing valve flange leaking.

Please check that the orifice plate changer for b-E28-B is not leaking

Inspection in the meter cabinets was limited. The control valves in meter cabinets should be checked for leakage.

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

| | |
|---|--|
| <p>Non-Compliance Number: 2026-0301-01</p> <p>Issued Date: '2026-05-12'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 30 Days</p> <p>Correction Due Date: '2026-06-11'</p> | <p>Permit: 100114385 Facility ID: 00027455 Facility Name: PETRONAS TOWN A-028-B/094-G-01 001 Facility Type: Well Facility Location: NTS: A- 028-B/094-G-01</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;</p> |
| <p>Non-Compliance Comment:</p> | |

Authorized by BCER



Non-Compliance Notice Number: 2026-0301
Issued Date: 2026-05-12

Letter ID: L2602179
Letter Date: 2026-05-12