

Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
 Discovery Date: 2026-05-12
 As a result of Inspection 2026-1537

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0305-01</p> <p>Issued Date: '2026-05-13'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date: '2026-05-27'</p>	<p>Permit: 100055849 Well ID: 21711 Well Name: CNRL HZ W STODDART 09-12-086-21 Location: DLS: 09-12-086-21</p> <p>Legislation: Energy Resource Activities Act 37 (1) A permit holder and a person carrying out an energy resource activity must (a) prevent spillage, and</p>
<p>Non-Compliance Comment: x2 plugs missing from needle valves (See attached) on wellhead and flowline.</p>	

<p>Non-Compliance Number: 2026-0305-02</p> <p>Issued Date: '2026-05-13'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p>	<p>Permit: 100055849 Well ID: 21711 Well Name: CNRL HZ W STODDART 09-12-086-21 Location: DLS: 09-12-086-21</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;</p>
---	--

Correction Due Date: '2026-05-27'	
Non-Compliance Comment: Stuffing box leaking fluid down well and onto ground (See attached).	

Authorized by BCER