

## Non-Compliance Notice - Issued

Permit Holder: Pacific Canbriam Energy Limited  
Discovery Date: 2026-05-13  
As a result of Inspection 2026-1553

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

|   |   |
|---|---|
| <p><b>Non-Compliance Number:</b><br/><b>2026-0308-01</b></p> <p><b>Issued Date:</b><br/><b>'2026-05-15'</b></p> <p><b>Status:</b><br/><b>Issued</b></p> <p><b>Outcome:</b></p> <p><b>Correction Duration:</b><br/><b>14 Days</b></p> <p><b>Correction Due Date:</b><br/><b>'2026-05-29'</b></p> | <p>Permit: 100079681<br/>Facility ID: 00018164<br/>Facility Name: PACIFIC CANBRIAM ALTARES C-084-A/094-B-08 001<br/>Facility Type: Well Facility<br/>Location: NTS: C- 084-A/094-B-08</p> <p><b>Legislation:</b><br/>Drilling and Production Regulation<br/>78 (6) A facility permit holder must ensure both of the following:<br/>(a) the facility is maintained in a condition that minimizes hazards, including hazards associated with pits, holes, equipment and storage of materials;</p> |
| <p><b>Non-Compliance Comment:</b> There is a piling hole on the east side of the water building that is not noticeable and is deep. The Operations Roamer was with me so they are aware of its exact location.</p>  |   |

---

Authorized by BCER