

Non-Compliance Notice - Issued

Permit Holder: PETRONAS Energy Canada Ltd.
Discovery Date: 2026-05-25
As a result of Inspection 2026-1701

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

| | |
|---|--|
| <p>Non-Compliance Number: 2026-0317-01</p> <p>Issued Date: '2026-05-26'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date: '2026-06-09'</p> | <p>Permit: 100078130 Well ID: 29223 Well Name: PETRONAS HZ CARIBOU C- 049-J/094-G-07 Location: NTS: C- 049-J/094-G-07</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (b) contain and eliminate the spillage;</p> |
| <p>Non-Compliance Comment:</p> <p>LEL and H2S detected from surface casing vent. The nature of the of H2S from the SCV and intention of the Company to re-install a burst plate merits a 14 day timeline to address the non-compliance.</p> | |

Authorized by BCER