

Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
Discovery Date: 2026-06-02
As a result of Inspection 2026-1807

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0338-01</p> <p>Issued Date: '2026-06-03'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date: '2026-06-17'</p>	<p>Permit: 100005445 Well ID: 03853 Well Name: CNRL OSPREY D- 057-J/094-A-15 Location: NTS: D- 057-J/094-A-15</p> <p>Legislation: Energy Resource Activities Act 37 (1) A permit holder and a person carrying out an energy resource activity must (a) prevent spillage, and</p>
<p>Non-Compliance Comment: Plug missing from needle valve on top of wellhead (See attached)</p>	

<p>Non-Compliance Number: 2026-0338-02</p> <p>Issued Date: '2026-06-03'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 30 Days</p> <p>Correction Due Date:</p>	<p>Permit: 100005445 Well ID: 03853 Well Name: CNRL OSPREY D- 057-J/094-A-15 Location: NTS: D- 057-J/094-A-15</p> <p>Legislation: Drilling and Production Regulation 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (a) suspend the well in a manner that ensures the ongoing integrity of the well;</p>
---	---

'2026-07-03'	
Non-Compliance Comment: Valve handles on wellhead not chained & locked, or removed (See attached).	

Authorized by BCER