

Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
 Discovery Date: 2026-06-02
 As a result of Inspection 2026-1829

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0343-01</p> <p>Issued Date: '2026-06-03'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 30 Days</p> <p>Correction Due Date: '2026-07-03'</p>	<p>Permit: 100046660 Well ID: 19151 Well Name: CNRL W PEEJAY A-A019-H/094-A-15 Location: NTS: A-A019-H/094-A-15</p> <p>Legislation: Drilling and Production Regulation 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (a) suspend the well in a manner that ensures the ongoing integrity of the well;</p>
<p>Non-Compliance Comment: Valve handle not chained & locked or removed (See attached).</p>	

<p>Non-Compliance Number: 2026-0343-02</p> <p>Issued Date: '2026-06-03'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p> <p>Correction Due Date:</p>	<p>Permit: 100046660 Well ID: 19151 Well Name: CNRL W PEEJAY A-A019-H/094-A-15 Location: NTS: A-A019-H/094-A-15</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;</p>
---	---

'2026-06-17'	
<p>Non-Compliance Comment: Audible hissing coming from needle valve on wellhead (See attached). Occasional High & low LEL alarms on personal monitor when in close proximity to wellhead. Odors downwind of wellhead.</p>	

Authorized by BCER