

## Non-Compliance Notice - Issued

Permit Holder: Pacific Canbriam Energy Limited  
Discovery Date: 2026-06-10  
As a result of Inspection 2026-1993

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p><b>Non-Compliance Number:</b> <b>2026-0376-01</b></p> <p><b>Issued Date:</b> <b>'2026-06-15'</b></p> <p><b>Status:</b> <b>Issued</b></p> <p><b>Outcome:</b></p> <p><b>Correction Duration:</b> <b>30 Days</b></p> <p><b>Correction Due Date:</b> <b>'2026-07-15'</b></p>	<p>Permit: 100102996 Well ID: 33919 Well Name: PACIFIC CANBRIAM HZ ALTARES C-H017-H/094-B-08 Location: NTS: C-H017-H/094-B-08</p> <p><b>Legislation:</b> Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;</p>
<p><b>Non-Compliance Comment:</b> The c-h-17 wellhead is leaking at the upper and lower master valves as evident by the build up of produced water precipitate.</p>	

---

Authorized by BCER