

## Non-Compliance Notice - Issued

Permit Holder: Yoho Resources Inc.  
Discovery Date: 2026-06-11  
As a result of Inspection 2026-1995

**Notice Comment:**

a-1-19 meter skid-the PSV off the fuel gas scrubber is not vented to the outside.

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: <b>2026-0377-01</b></p> <p>Issued Date: <b>'2026-06-15'</b></p> <p>Status: <b>Issued</b></p> <p>Outcome:</p> <p>Correction Duration: <b>14 Days</b></p> <p>Correction Due Date: <b>'2026-06-29'</b></p>	<p>Permit: 100079379 Well ID: 29915 Well Name: YOHO HZ INGA A01-19-087-23 Location: DLS: A01-19-087-23</p> <p>Legislation: Drilling and Production Regulation 16 (1) A well permit holder must ensure (a) that all tools and equipment used in well operations, production, injection or disposal are installed and operated in accordance with the manufacturer's specifications or sound engineering practices,</p>
<p>Non-Compliance Comment: a-1-19 meter skid-the PSV for the fuel gas scrubber is not vented to the outside of the skid.</p>	

---

Authorized by BCER