

## Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited  
Discovery Date: 2026-06-16  
As a result of Inspection 2026-2061

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p><b>Non-Compliance Number:</b> <b>2026-0393-01</b></p> <p><b>Issued Date:</b> <b>'2026-06-22'</b></p> <p><b>Status:</b> <b>Issued</b></p> <p><b>Outcome:</b></p> <p><b>Correction Duration:</b> <b>30 Days</b></p> <p><b>Correction Due Date:</b> <b>'2026-07-22'</b></p>	<p>Permit: 100013241 Well ID: 07784 Well Name: CNRL ET AL HELMET B- 050-I/094-P-10 Location: NTS: B- 050-I/094-P-10</p> <p>Legislation: Drilling and Production Regulation 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (b) ensure positive isolation between the well and the flowline by disconnecting the well from the flowline or by other means.</p>
<p><b>Non-Compliance Comment:</b> Wellhead flowlines are connected to well/facility (not disconnected or blinded (no positive isolation at wellhead)); no gas production has been reported in KERMIT since 2024-09 (&gt; 14 months).</p> <p>All wellhead valve handles were observed to be chained and locked.</p>	

---

Authorized by BCER