

Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
Discovery Date: 2026-06-16
As a result of Inspection 2026-2063

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

| | |
|--|--|
| <p>Non-Compliance Number: 2026-0395-01</p> <p>Issued Date: '2026-06-22'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 30 Days</p> <p>Correction Due Date: '2026-07-22'</p> | <p>Permit: 100011788 Well ID: 07355 Well Name: CNRL ET AL HELMET A- 041-A/094-P-15 Location: NTS: A- 041-A/094-P-15</p> <p>Legislation: Drilling and Production Regulation 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (b) ensure positive isolation between the well and the flowline by disconnecting the well from the flowline or by other means.</p> |
| <p>Non-Compliance Comment: Wellhead flowlines are connected to well/facility (not disconnected or blinded (no positive isolation at wellhead)); no gas production has been reported in KERMIT since 2023-12 (> 14 months).</p> <p>All wellhead valve handles were observed to be chained and locked.</p> | |

Authorized by BCER