

## Non-Compliance Notice - Issued

Permit Holder: Bench Creek Resources Ltd.  
Discovery Date: 2026-06-18  
As a result of Inspection 2026-2084

**Notice Comment:**

Last gas production August 2022. Well suspension is required under DPR 25(5). Please ensure positive isolation between the well and flowline, and suspend the wellhead by removing or chaining/locking the wellhead valve handles.

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: <b>2026-0402-01</b></p> <p>Issued Date: <b>'2026-06-23'</b></p> <p>Status: <b>Issued</b></p> <p>Outcome:</p> <p>Correction Duration: <b>30 Days</b></p> <p>Correction Due Date: <b>'2026-07-23'</b></p>	<p>Permit: 100051541 Well ID: 20471 Well Name: BENCH CREEK RES ET AL EKWAN A- 025-E/094-I-10 Location: NTS: A- 025-E/094-I-10</p> <p>Legislation: Drilling and Production Regulation - 25 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (a) suspend the well in a manner that ensures the ongoing integrity of the well; (b) ensure positive isolation between the well and the flowline by disconnecting the well from the flowline or by other means.</p>
<p>Non-Compliance Comment: Last gas production August 2022. Well suspension is required under DPR 25(5). Please ensure positive isolation between the well and flowline, and suspend the wellhead by removing or chaining/locking the wellhead valve handles.</p>	

---

Authorized by BCER