

Non-Compliance Notice - Issued

Permit Holder: Procyon Energy Corp.
Discovery Date: 2026-06-23
As a result of Inspection 2026-2126

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0410-01</p> <p>Issued Date: '2026-06-26'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 30 Days</p> <p>Correction Due Date: '2026-07-26'</p>	<p>Permit: 100007111 Well ID: 05012 Well Name: PROCYON RIGEL 06-30-087-18 Location: DLS: 06-30-087-18</p> <p>Legislation: Drilling and Production Regulation 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (a) suspend the well in a manner that ensures the ongoing integrity of the well;</p>
<p>Non-Compliance Comment: Valve handles are chained and locked but are so loose valve handles are not secure (See attached).</p>	

<p>Non-Compliance Number: 2026-0410-02</p> <p>Issued Date: '2026-06-26'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 14 Days</p>	<p>Permit: 100007111 Well ID: 05012 Well Name: PROCYON RIGEL 06-30-087-18 Location: DLS: 06-30-087-18</p> <p>Legislation: Energy Resource Activities Act 37 (1) A permit holder and a person carrying out an energy resource activity must (a) prevent spillage, and</p>
---	--

Correction Due Date: '2026-07-10'	
Non-Compliance Comment: Valve on flow line going into ground missing bull plug (See attached).	

Authorized by BCER