

## Non-Compliance Notice - Issued

Permit Holder: Tourmaline Oil Corp.  
Discovery Date: 2026-07-02  
As a result of Inspection 2026-2220

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: <b>2026-0431-01</b></p> <p>Issued Date: <b>'2026-07-03'</b></p> <p>Status: <b>Issued</b></p> <p>Outcome:</p> <p>Correction Duration: <b>30 Days</b></p> <p>Correction Due Date: <b>'2026-08-02'</b></p>	<p>Permit: 100079262 Well ID: 29270 Well Name: TOURMALINE HZ PICKELL D-A083-F/094-H-03 Location: NTS: D-A083-F/094-H-03</p> <p>Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;</p>
<p>Non-Compliance Comment: H2S detected in meter building during entry test &amp; retest on personal monitor.</p>	

---

Authorized by BCER