

## Non-Compliance Notice - Issued

Permit Holder: Ovintiv Canada ULC  
 Discovery Date: 2026-07-08  
 As a result of Inspection 2026-2277

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: <b>2026-0447-01</b></p> <p>Issued Date: <b>'2026-07-09'</b></p> <p>Status: <b>Issued</b></p> <p>Outcome:</p> <p>Correction Duration: <b>30 Days</b></p> <p>Correction Due Date: <b>'2026-08-08'</b></p>	<p>Permit: 100067191          Road Number: 00600          Segment IDs (Location):          001 (From NTS: B- 016-C/093-P-10 To NTS: D- 086-K/093-P-07)</p> <p>Legislation:          Energy Resource Road Regulation          (1) A road permit holder must              (a) ensure that road surface and slope drainage systems, including inlets, drainage structures, ditches, culverts, bridges, road crowning, insloping and outsloping, are functional,</p>
<p>Non-Compliance Comment: Appears beaver activity has plugged culvert and causing water to wash over the road surface. Beaver damming flow over the road. See attached pictures.</p>	

---

Authorized by BCER