

Non-Compliance Notice - Issued

Permit Holder: Ovintiv Canada ULC
Discovery Date: 2026-07-15
As a result of Inspection 2026-2485

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0486-01 Issued Date: '2026-07-17' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date: '2026-08-16'	Permit: 100030664 Well ID: 14101 Well Name: OVV ET AL TUPPER A- 062-F/093-P-08 Location: NTS: A- 062-F/093-P-08 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
Non-Compliance Comment: Leak from nut left side of master valve.	

Authorized by BCER