

Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
Discovery Date: 2026-07-16
As a result of Inspection 2026-2566

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0494-01 Issued Date: '2026-07-20' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date: '2026-08-19'	Permit: 100022410 Well ID: 11399 Well Name: CNRL BULRUSH C- 079-F/094-A-16 Location: NTS: C- 079-F/094-A-16 Legislation: Drilling and Production Regulation 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (a) suspend the well in a manner that ensures the ongoing integrity of the well;
Non-Compliance Comment: The polish rod remains in the well not connected to the pumpjack. Pumpjack has been removed, but the polish rod remains in the wellhead. As per the Guidelines, the polish rod must stay connected to the pumpjack for well suspension.	

Authorized by BCER