

Non-Compliance Notice - Issued

Permit Holder: Tourmaline Oil Corp.
Discovery Date: 2026-07-22
As a result of Inspection 2026-2594

Notice Comment:

Weeping of packing nut on valve on pipe rack side of meter cabinet causing staining below on the ground.

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0502-01 Issued Date: '2026-07-24' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date: '2026-08-23'	Permit: 100102983 Well ID: 34036 Well Name: TOURMALINE HZ TOWN A-B032-I/094-B-09 Location: NTS: A-B032-I/094-B-09 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
Non-Compliance Comment: Packing nut on valve is weeping causing a stain below on the ground. Valve is located on the pipe rack side of the meter cabinet.	

Authorized by BCER