

Non-Compliance Notice - Issued

Permit Holder: ConocoPhillips Canada Resources Corp.
Discovery Date: 2026-08-11
As a result of Inspection 2026-2876

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0544-01 Issued Date: '2026-08-12' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date: '2026-09-11'	Permit: 100012240 Well ID: 07519 Well Name: COP FIREWEED B- 050-D/094-A-14 Location: NTS: B- 050-D/094-A-14 Legislation: Drilling and Production Regulation 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (a) suspend the well in a manner that ensures the ongoing integrity of the well;
Non-Compliance Comment: Valve handles are chained but not locked secure (See attached).	

Authorized by BCER