

Non-Compliance Notice - Issued

Permit Holder: ConocoPhillips Canada Resources Corp.

Discovery Date: 2026-08-11

As a result of Inspection 2026-2877

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0545-01 Issued Date: '2026-08-12' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date: '2026-09-11'	Permit: 100059095 Well ID: 22660 Well Name: COP FIREWEED D- 030-D/094-A-14 Location: NTS: D- 030-D/094-A-14 Legislation: Drilling and Production Regulation 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (a) suspend the well in a manner that ensures the ongoing integrity of the well;
Non-Compliance Comment: Wing valve handle not chained, locked & secure or removed (See attached).	

Authorized by BCER