

Non-Compliance Notice - Issued

Permit Holder: Canlin Energy Corporation
Discovery Date: 2026-08-20
As a result of Inspection 2026-2987

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0560-01 Issued Date: '2026-08-21' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date: '2026-09-20'	Permit: 100000919 Well ID: 00715 Well Name: CANLIN LAPRISE A- 022-E/094-H-05 Location: NTS: A- 022-E/094-H-05 Legislation: Drilling and Production Regulation 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (b) ensure positive isolation between the well and the flowline by disconnecting the well from the flowline or by other means. Non-Compliance Comment: Wellhead valve handles (2x - master and wing valve handle) are not disabled (chained/locked or removed) and well flowline is not isolated (disconnected / blinded). KERMIT last reported gas production date: 2025-04 (> 16 months no gas production).
---	--

Non-Compliance Number: 2026-0560-02 Issued Date: '2026-08-21' Status: Issued Outcome:	Permit: 100000919 Well ID: 00715 Well Name: CANLIN LAPRISE A- 022-E/094-H-05 Location: NTS: A- 022-E/094-H-05 Legislation: Drilling and Production Regulation 18 (9) A well permit holder must ensure that a well is configured such that (c) the surface casing is equipped with an open valve.
--	--

Correction Duration: 14 Days Correction Due Date: '2026-09-04'	
Non-Compliance Comment: Wellhead SCVA is not attached to well: SCVA pipe/ball valve is found detached from wellhead and laying on ground adjacent to well.	

Authorized by BCER