

Non-Compliance Notice - Issued

Permit Holder: Saba Oil & Gas Ltd.
Discovery Date: 2026-08-20
As a result of Inspection 2026-3015

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0565-01 Issued Date: '2026-08-21' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-09-04'	Permit: 100057358 Facility ID: 00022578 Facility Name: SABA O&G LAPRISECREEK C-001-H/094-G-08 001 Facility Type: Well Facility Location: NTS: C- 001-H/094-G-08 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
Non-Compliance Comment: LEL gas was measured (Altair-5x) at flowline: ARGUS control valve.	

Non-Compliance Number: 2026-0565-02 Issued Date: '2026-08-21' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date:	Permit: 100057358 Well ID: 22244 Well Name: SABA O&G LAPRISE C- 001-H/094-G-08 Location: NTS: C- 001-H/094-G-08 Legislation: Drilling and Production Regulation 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (b) ensure positive isolation between the well and the flowline by disconnecting the well from the flowline or by other means.
--	--

'2026-09-20'	
Non-Compliance Comment: Wellhead is not isolated from the flowline (not blinded/disconnected). All wellhead valve handles have been removed. KERMIT last submitted reported gas production date: 2025-03 (> 17 months no gas production).	

Authorized by BCER