

Non-Compliance Notice - Issued

Permit Holder: Saba Oil & Gas Ltd.
Discovery Date: 2026-08-20
As a result of Inspection 2026-3017

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0567-01 Issued Date: '2026-08-21' Status: Issued Outcome: Correction Duration: 14 Days Correction Due Date: '2026-09-04'	Permit: 100000630 Well ID: 00490 Well Name: SABA O&G LAPRISE A- 081-A/094-G-08 Location: NTS: A- 081-A/094-G-08 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage;
Non-Compliance Comment: LEL gas was measured (Altair-5x) at the wellhead master valve handle (packing leak). Note: Suspended status requires that the wellhead flowline is isolated as close as possible to wellhead: presently a blind is installed at pipeline connection. Please ensure wellhead flowline is isolated (blinded/disconnected) as close as possible to wellhead. Wellhead: master (1x) and lower wing valve (2x) handles are not all chained and locked (or removed) (required if well is to be managed/proceed to "Suspended Status). KERMIS last reported gas production date: 2025-09 (> 11 months no gas production).	



Non-Compliance Notice Number: 2026-0567
Issued Date: 2026-08-21

Letter ID: L2604271
Letter Date: 2026-08-21

Authorized by BCER