

## Non-Compliance Notice - Issued

Permit Holder: Tourmaline Oil Corp.  
Discovery Date: 2026-08-26  
As a result of Inspection 2026-3152

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

|                                                                                                                                                                                                                                                       |                                                                                                                                                                                                                                                                                                             |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p>Non-Compliance Number:<br/><b>2026-0599-01</b></p> <p>Issued Date:<br/><b>'2026-08-28'</b></p> <p>Status:<br/><b>Issued</b></p> <p>Outcome:</p> <p>Correction Duration:<br/><b>14 Days</b></p> <p>Correction Due Date:<br/><b>'2026-09-11'</b></p> | <p>Permit: 100031067<br/>Well ID: 14250<br/>Well Name: TOURMALINE NIG C- 001-G/094-H-04<br/>Location: NTS: C- 001-G/094-H-04</p> <p>Legislation:<br/>Energy Resource Activities Act<br/>37 (1) A permit holder and a person carrying out an energy resource activity must<br/>(a) prevent spillage, and</p> |
| <p>Non-Compliance Comment: 1/4 turn discharge valve on secondary containment missing plug (See attached).</p>                                                                                                                                         |                                                                                                                                                                                                                                                                                                             |

---

Authorized by BCER